

Gasket failure at an asphalt plant resulted in a bitumen spill. Some of the bitumen, which was at a temperature of circa 130 - 140 degrees, enveloped an airline that ruptured causing a spray of the bitumen.

WHAT HAPPENED

A failure in the bitumen trace heating system on an asphalt plant resulted in the pipework cooling. After the trace heating was repaired the pipework was brought back to the operating temperature. The plant was then started successfully, mixing 6 tonnes without any problems. However, as the manager passed by the bitumen system, he observed bitumen leaking beneath the pump cover box. He promptly notified the plant operator, leading to the shutdown of the equipment. It was also discovered that some of the bitumen, which was at a temperature of circa 130 - 140 degrees, had enveloped an airline that ruptured causing a spray of the bitumen. See full incident alert for more information.



LEARNING POINTS / ACTIONS TAKEN

LOCATION: ASPHALT/COATING PLANT
ACTIVITY: MAINTENANCE & HOUSEKEEPING
SUB ACTIVITY: ASPHALT & COATED STONE

ALERT STATUS: Normal
DATE ISSUED: 21/10/2024 15:52:13
INCIDENT No: 04840