


Faulty source of WATA ARyo

E NAD NATT xmx p

The log wa sr sm Gvr oa l oe l the wou y ey peW
 ue - oae wok the tr i wl . Qr oklok the
 .lr si fu er Vr tei l o the ll r alok Qn- te l . r b c
 y r We r kk Vr te a Wake WGW WI - oae wok
 the tr i wFthe Shr a r otl Qsr tea thr t i l y e pl Iti
 ul - la pe i e l Ce a r oa the w. l w ul - la wU- l w
 k w alok l ..mThe SWLi ea r seW l t t l u l wF
 loQ- alok T() i . l W he g p r oa Q oa- Qea r
 tl l lpl , tr l w) ssW, ly r tel SAP y lo- tei r .teW
 i tr Wok the g p the dG ur i Q ttlok thW- kh r pl It
 r oa y l Nea the k w a e W ur Stl Qhe Qw l o the
 sWk w i l . the ul W w o al lok i l the dG
 lor a Ne w e ot l S w y l Nea h l i W k h t hr oa . W y the
 k w a e W oa Q - k h t h l i . l o k e W o the k w a l o k a l i Q
 u h l l e W s l r Q o k h l i hr o a m The a l i Q Q t thW- kh h l i
 k l l Ne r oa Q - i e a r 1 Q y Q t l o the l - t i l a e l . h l i
 W k h t l o a e , . l o k e W (e r l l i l o k h e hr a l o g W a h l y i e l . F
 the dG t- W e a l .. the k w a e W l o . l W e a the l the W
 Q u y ey peW . h l i l o g V S r oa y r a e h l i ur Stl
 the p w a k e t l i e e w . l m r l a t w r ty e o t m The l the W
 Q u y ey peW s w i e o t y r a e the ul W i l t e i r . e p S
 t- W l o k the k w a e W .. r t the sl u e W l - W e r oa
 y r a e h l i ur Stl the p w a k e t l s W N a e r i i l i t r o Q e
 r i w U- l w a m x h l i t the w u r i r G e W l t t l x l W w
 r oa (l i w) i i e i y e o t l o s l r Q e F the l o g V S l Q Q W a

allowing power to flow through the fuses

There were no physical indications on the FCU to suggest that there was a problem of this magnitude.



Example of FCU

LEARNING POINTS / ACTIONS TAKEN

The FCU was replaced by a competent electrical contractor.

The Lock-Off and Isolation Procedures throughout the company must be amended to include testing every time that access is required inside a panel (to, for example, replace fuses or reset trips): to ensure that all parts to be handled are de-energised. The isolator handle cannot always be trusted to do this.

The foregoing applies to all aspects of business, not just Quarries.

The outcome in this incident could have been very different had the manager not carried out testing before attempting to remove fuses.

LOCATION:

QUARRY

ACTIVITY:

MAINTENANCE & HOUSEKEEPING

SUB ACTIVITY:

N/A

ALERT STATUS:

Normal

DATE ISSUED:

12/08/2011

INCIDENT No:

00295