

# Fatal 5 - Excavator struck by falling rock

## WHAT HAPPENED

During face loadout operation at a hard rock quarry, a large piece of stone (weighing approximately 6 tonnes) toppled a short distance from the side of the blast-pile and struck the nearside of a CAT 390 excavator, causing damage to the machine's retractable access steps. No one was hurt in the incident.

### Key Findings

- Although there was a suitable rock trap in front of the machine the rock trap at the nearside of the machine was not sufficient to contain the piece of rock.
- The excavator operator was very experienced and fully qualified having had formal face excavator and geotechnical training – he had operated front line face machinery for many years.



## LEARNING POINTS / ACTIONS TAKEN

- In accordance with QNJAC guidance, operators must ensure that; “there is a suitably designed rock trap in place, which as a rule of thumb should be  $\frac{1}{2}$  of the face height in depth and  $\frac{1}{4}$  of the face height in width” to capture and contain any rocks that fall from the face / blast pile during load out.
- The task specific E&T job cards are to be reviewed and reissued to all face operatives, along with re-training, to ensure safe working requirements are clearly understood and complied with at all times.
- If you are unable to comply with standard safe working practices ‘STOP THE JOB’ and speak to your supervisor or line manager to discuss and review the safest way forward.
- You could led a **Team Discussion** (*remember to involve colleagues, regular contractors and hauliers in your discussion*) - Could a similar incident happen on our site and if so, what are we going to do to make sure it doesn't?

---

**LOCATION:**

**QUARRY**

**ACTIVITY:**

**PRODUCTION AND PROCESSING**

**SUB ACTIVITY:**

**FACE ACTIVITY**

**ALERT STATUS:**

**Normal**

**DATE ISSUED:**

**09/08/2022 14:04:46**

**INCIDENT No:**

**03624**