

Storm winds damaged metal cladding at high level that came detached

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

---

LOCATION:	CEMENT PLANT	ALERT STATUS:	Normal
ACTIVITY:	WEATHER RELATED INCIDENT	DATE ISSUED:	12/09/2024 13:27:56
SUB ACTIVITY:	NO SUB ACTIVITY AVAILABLE	INCIDENT No:	03783