Whilst stripping and dismantling a scaffolding inside, a 6ft tube has fallen 30ft, impacting on handrails and walkways, reaching the ground floor. An exclusion zone was in place directly underneath the dismantling operation, however the tube has fallen outside of this zone.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION: ACTIVITY: SUB ACTIVITY: CEMENT PLANT MAINTENANCE & HOUSEKEEPING CEMENT

ALERT STATUS: DATE ISSUED: INCIDENT No: Normal 12/09/2024 13:37:33 03784