

**A concern was raised regarding the condition of a section of ducting (5t) which had been installed as part of the new bag filter project. Potential to fall.**

## **WHAT HAPPENED**

## **LEARNING POINTS / ACTIONS TAKEN**

---

<b>LOCATION:</b>	<b>CEMENT PLANT</b>	<b>ALERT STATUS:</b>	<b>Normal</b>
<b>ACTIVITY:</b>	<b>MAINTENANCE &amp; HOUSEKEEPING</b>	<b>DATE ISSUED:</b>	<b>12/09/2024 13:53:58</b>
<b>SUB ACTIVITY:</b>	<b>CEMENT</b>	<b>INCIDENT No:</b>	<b>03786</b>