

**RIDDOR - Structural failure of the harbour wall, while on-going construction works were underway to repair and renovate. The movement of the structure was being monitored at the time of collapse, and the area was isolated, and made safe while design issues were addressed.**

## **WHAT HAPPENED**

## **LEARNING POINTS / ACTIONS TAKEN**

---

<b>LOCATION:</b>	<b>MARINE &amp; SHIP TO SHORE</b>	<b>ALERT STATUS:</b>	<b>Normal</b>
<b>ACTIVITY:</b>	<b>MAINTENANCE &amp; HOUSEKEEPING</b>	<b>DATE ISSUED:</b>	<b>12/09/2024 13:56:48</b>
<b>SUB ACTIVITY:</b>	<b>SHIP TO SHORE</b>	<b>INCIDENT No:</b>	<b>03787</b>