

RIDDOR - Structural failure of the harbour wall, while on-going construction works were underway to repair and renovate. The movement of the structure was being monitored at the time of collapse, and the area was isolated, and made safe while design issues were addressed.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	MARINE & SHIP TO SHORE	ALERT STATUS:	Normal
ACTIVITY:	MAINTENANCE & HOUSEKEEPING	DATE ISSUED:	12/09/2024 13:56:48
SUB ACTIVITY:	SHIP TO SHORE	INCIDENT No:	03787