

Section of pre-netted face which had failed at high level resulting in a minor rock fall. Some rocks are left suspended on the damaged netting

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	MASONRY WORKS	ALERT STATUS:	Normal
ACTIVITY:	QUARRYING AND FACE ACTIVITY	DATE ISSUED:	13/09/2024 11:44:06
SUB ACTIVITY:	NO SUB ACTIVITY AVAILABLE	INCIDENT No:	03794