Guarding broke up under material spillage, this happened in an area above the stair case.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION: ACTIVITY: SUB ACTIVITY: CEMENT PLANT PRODUCTION AND PROCESSING CEMENT PRODUCTION ALERT STATUS: DATE ISSUED: INCIDENT No: Normal 13/09/2024 12:19:59 03801