

**FLT driver was transporting product when the FLT hit a small bump causing the FLT door to open. The door then caught a stack of product resulting in damage to the door and causing the window in the bottom panel to break. The drivers window was open during operation.**

## **WHAT HAPPENED**

## **LEARNING POINTS / ACTIONS TAKEN**

---

**LOCATION:** CONCRETE PRODUCTS PLANT  
**ACTIVITY:** STOCKPILING AND STACKING  
**SUB ACTIVITY:** NO SUB ACTIVITY AVAILABLE

**ALERT STATUS:** Normal  
**DATE ISSUED:** 13/09/2024 13:15:54  
**INCIDENT No:** 04804