

FLT driver was transporting product when the FLT hit a small bump causing the FLT door to open. The door then caught a stack of product resulting in damage to the door and causing the window in the bottom panel to break. The drivers window was open during operation.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

| | | | |
|----------------------|----------------------------------|----------------------|----------------------------|
| LOCATION: | CONCRETE PRODUCTS PLANT | ALERT STATUS: | Normal |
| ACTIVITY: | STOCKPILING AND STACKING | DATE ISSUED: | 13/09/2024 13:15:54 |
| SUB ACTIVITY: | NO SUB ACTIVITY AVAILABLE | INCIDENT No: | 04804 |