

Truck Mixer Overturn

WHAT HAPPENED

A fully laden truck mixer delivering concrete to a customer site overturned while travelling around a roundabout. The driver suffered a fractured wrist that required surgery. Fortunately, no other vehicles or people were involved..

Key Findings from the Investigation:

- The truck mixer was travelling at 18-20 mph
- The rear wheels of the truck clipped the inside kerb of the roundabout the moment before it overturned
- The driver was wearing his seatbelt, saving him from a more serious injury
- The driver had only been driving a truck mixer for three months
- The driver had not had the Company 'How to Avoid Truck Mixer Overturns' briefing



LEARNING POINTS / ACTIONS TAKEN

Learning Points

- Check that all drivers have had the appropriate company briefing such as 'How to Avoid Truck Mixer Overturns'; this includes; employed, contracted and hired drivers.
 - Ensure that all new truck mixer drivers receive the appropriate company briefings such as 'Driver Safety Essentials' and 'How to Avoid Truck Mixer Overturns', as part of their induction.
 - Slow down for bends, corners and roundabouts
 - Always wear your seatbelt
-

LOCATION:	ON-HIGHWAY	ALERT STATUS:	Normal
ACTIVITY:	TRANSPORT & LOGISTICS / DELIVERY	DATE ISSUED:	11/07/2016 12:32:34
SUB ACTIVITY:	ON-HIGHWAY	INCIDENT No:	01435