

Isolation Breach - plant was re-energised prior to replacement of the head-drum guard on the batch belt.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION: READYMIX OR MORTAR PLANT
ACTIVITY: MAINTENANCE & HOUSEKEEPING
SUB ACTIVITY: CONVEYORS

ALERT STATUS: Normal
DATE ISSUED: 03/09/2024 16:54:11
INCIDENT No: 03734