

**Isolation Breach - Arc flash was reported to have been from a set of gland pliers (grips) falling onto the live outgoing terminals of a moulded case circuit breaker . The grips were being used to isolate the shaft of the panel at the time.**

## **WHAT HAPPENED**

## **LEARNING POINTS / ACTIONS TAKEN**

---

<b>LOCATION:</b>	<b>QUARRY</b>	<b>ALERT STATUS:</b>	<b>Normal</b>
<b>ACTIVITY:</b>	<b>MAINTENANCE &amp; HOUSEKEEPING</b>	<b>DATE ISSUED:</b>	<b>03/09/2024 17:27:23</b>
<b>SUB ACTIVITY:</b>	<b>PLANT CONTROLS AND SENSORS</b>	<b>INCIDENT No:</b>	<b>03744</b>