

Isolation Breach - Arc flash was reported to have been from a set of gland pliers (grips) falling onto the live outgoing terminals of a moulded case circuit breaker . The grips were being used to isolate the shaft of the panel at the time.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	QUARRY	ALERT STATUS:	Normal
ACTIVITY:	MAINTENANCE & HOUSEKEEPING	DATE ISSUED:	03/09/2024 17:27:23
SUB ACTIVITY:	PLANT CONTROLS AND SENSORS	INCIDENT No:	03744