

Isolation Breach - Arc flash was reported to have been from a set of gland pliers (grips) falling onto the live outgoing terminals of a moulded case circuit breaker . The grips were being used to isolate the shaft of the panel at the time.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

| | | | |
|---------------|----------------------------|---------------|---------------------|
| LOCATION: | QUARRY | ALERT STATUS: | Normal |
| ACTIVITY: | MAINTENANCE & HOUSEKEEPING | DATE ISSUED: | 03/09/2024 17:27:23 |
| SUB ACTIVITY: | PLANT CONTROLS AND SENSORS | INCIDENT No: | 03744 |