



Telehandler parked up in the workshop forecourt by the operator. After exiting the vehicle, approx 3 minutes later, the telehandler rolled away down the forecourt ramp where it came to a halt due to the forks digging into the ground. Estimated travel was 15m. Hand brake had not been applied.



		!	"			!	# \$
% "			&	% "		!	' (' () ') * +) + ,) '
! -	% "	-	!	"		#	' ./ O (