

Whilst stripping and dismantling a scaffolding inside, a 6ft tube has fallen 30ft, impacting on handrails and walkways, reaching the ground floor. An exclusion zone was in place directly underneath the dismantling operation, however the tube has fallen outside of this zone.

## WHAT HAPPENED

## LEARNING POINTS / ACTIONS TAKEN

---

<b>LOCATION:</b>	<b>CEMENT PLANT</b>	<b>ALERT STATUS:</b>	<b>Normal</b>
<b>ACTIVITY:</b>	<b>MAINTENANCE &amp; HOUSEKEEPING</b>	<b>DATE ISSUED:</b>	<b>12/09/2024 13:37:33</b>
<b>SUB ACTIVITY:</b>	<b>CEMENT</b>	<b>INCIDENT No:</b>	<b>03784</b>