

**Delivery vehicle reversing towards spreader with body raised and twist locks / pins were removed. The rear tipper body door burst open, due to the weight sitting against it spilling load onto roadway**

## **WHAT HAPPENED**

## **LEARNING POINTS / ACTIONS TAKEN**

---

<b>LOCATION:</b>	<b>CONSTRUCTION/DELIVERY SITE</b>	<b>ALERT STATUS:</b>	<b>Normal</b>
<b>ACTIVITY:</b>	<b>TRANSPORT &amp; LOGISTICS / DELIVERY</b>	<b>DATE ISSUED:</b>	<b>13/09/2024 12:52:13</b>
<b>SUB ACTIVITY:</b>	<b>DELIVERING AGGREGATES</b>	<b>INCIDENT No:</b>	<b>04802</b>