

Delivery vehicle reversing towards spreader with body raised and twist locks / pins were removed. The rear tipper body door burst open, due to the weight sitting against it spilling load onto roadway

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	CONSTRUCTION/DELIVERY SITE	ALERT STATUS:	Normal
ACTIVITY:	TRANSPORT & LOGISTICS / DELIVERY	DATE ISSUED:	13/09/2024 12:52:13
SUB ACTIVITY:	DELIVERING AGGREGATES	INCIDENT No:	04802