FLT driver was transporting product when the FLT hit a small bump causing the FLT door to open. The door then caught a stack of product resulting in damage to the door and causing the window in the bottom panel to break. The drivers window was open during operation.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION: CONCRETE PRODUCTS PLANT ACTIVITY: STOCKPILING AND STACKING

SUB ACTIVITY: NO SUB ACTIVITY AVAILABLE

ALERT STATUS: Norm

DATE ISSUED: 13/09/2024 13:15:54

INCIDENT No: 04804