

**A lorry was parked side on to a type 1 stock pile to be loaded. A dumper has then tipped a load of type 1 over the edge protection causing it to go underneath the lorry and on the side.**

## **WHAT HAPPENED**

## **LEARNING POINTS / ACTIONS TAKEN**

---

<b>LOCATION:</b>	<b>QUARRY</b>	<b>ALERT STATUS:</b>	<b>Normal</b>
<b>ACTIVITY:</b>	<b>STOCKPILING AND STACKING</b>	<b>DATE ISSUED:</b>	<b>13/09/2024 13:20:52</b>
<b>SUB ACTIVITY:</b>	<b>NO SUB ACTIVITY AVAILABLE</b>	<b>INCIDENT No:</b>	<b>04806</b>