

Misfire - RIDDOR - Misfire occurred due to a surface connector not connected.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	QUARRY	ALERT STATUS:	Normal
ACTIVITY:	PRODUCTION AND PROCESSING	DATE ISSUED:	18/09/2024 13:23:34
SUB ACTIVITY:	FACE ACTIVITY	INCIDENT No:	04826