TRANSFOA - P FaaAt I - 15 RN69/15 Nable9/1Ft - NAdlfG

r i vePrvssucuk

A contractor was on-site at the quarry and whilst drilling the first row of holes, the face collapsed with approx. 100 tonnes of material falling to the quarry floor.

Please view incident alert 4841 for more information about what happened and recommended actions.

ouvnclebly leem rewely emergue

oy wely c W vwell le DW mE7 Rwell le DW TEvnnDicbRockPvwuRwehileD cyPrE7RwehileDRIvlov7ou vounePreveEnW kveuPrmEukW IcwikucePcFW C FNL Aa CYj: UJCUCYP: CNAWK UYOYC