

# Fatal 2 - TRANSPORT - FEL involved in collision

## WHAT HAPPENED

FEL was operating in the stock pile area when they proceeded to drive with the bucket in the elevated position obscuring their vision. A tipper was incorrectly parked and the FEL operator was unaware of them, resulting in a collision between the FEL and tipper.

## LEARNING POINTS / ACTIONS TAKEN

---

<b>LOCATION:</b>	<b>QUARRY</b>	<b>ALERT STATUS:</b>	<b>Normal</b>
<b>ACTIVITY:</b>	<b>STOCKPILING AND STACKING</b>	<b>DATE ISSUED:</b>	<b>05/06/2025 11:51:54</b>
<b>SUB ACTIVITY:</b>	<b>NO SUB ACTIVITY AVAILABLE</b>	<b>INCIDENT No:</b>	<b>04890</b>