Delivery vehicle reversing towards spreader with body raised and twist locks / pins were removed.The rear tipper body door burst open, due to the weight sitting against it spilling load onto roadway

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	**CONSTRUCTION/DELIVERY SITE**	**ALERT STATUS:**	**Normal**
ACTIVITY:	**TRANSPORT & LOGISTICS / DELIVERY**	**DATE ISSUED:**	**13/09/2024 12:52:13**
SUB ACTIVITY:	**DELIVERING AGGREGATES**	**INCIDENT No:**	**04802**