A lorry was parked side on to a type 1 stock pile to be loaded. A dumper has then tipped a load of type 1 over the edge protection causing it to go underneath the lorry and on the side.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	**QUARRY**	**ALERT STATUS:**	**Normal**
ACTIVITY:	**STOCKPILING AND STACKING**	**DATE ISSUED:**	**13/09/2024 13:20:52**
SUB ACTIVITY:	**NO SUB ACTIVITY AVAILABLE**	**INCIDENT No:**	**04806**