RIDDOR - Misfire - nothing unusual noted at time of blast.

WHAT HAPPENED

2 days later an unfired detonator and primer were found in shotpile. Subsequent clearance operations revealed a failure of connection between holes which meant 5 holes had misfired.

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	**QUARRY**	**ALERT STATUS:**	**Normal**
ACTIVITY:	**PRODUCTION AND PROCESSING**	**DATE ISSUED:**	**18/09/2024 12:46:30**
SUB ACTIVITY:	**FACE ACTIVITY**	**INCIDENT No:**	**04821**