A concern was raised regarding the condition of a section of ducting (5t) which had been installed as part of the new bag filter project. Potential to fall.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	**CEMENT PLANT**	**ALERT STATUS:**	**Normal**
ACTIVITY:	**MAINTENANCE & HOUSEKEEPING**	**DATE ISSUED:**	**12/09/2024 13:53:58**
SUB ACTIVITY:	**CEMENT, LIME AND SLAG**	**INCIDENT No:**	**03786**