A fatality has occurred whilst maintenance work was being undertaken on a conveyor
are advised to review their risk assessments and safe systems of work.

The following information is available on safequarry/youtube:

Safe Guarding: This presentation is intended to raise awareness of the issues surroun
prompt review of existing guarding by management and ensure guarding standards ar
level. http://www.safequarry.com/hotTopics/Safe%20Guarding%20Jun%2010%20-%2

Safety Alerts:
- Learning points from an incident where the light curtain failed
http://www.safequarry.com/IncidentReports/IncidentView.aspx?kincident=1441

- Learning points from a near miss from an improper isolation of a conveyor
http://www.safequarry.com/IncidentReports/IncidentView.aspx?kincident=393

Isolation Posters: Two posters designed to remind operators of the importance of follo
procedures
http://www.safequarry.com/resources/MPA%20Isolation%20Safety%20Poster%20Fru
http://www.safequarry.com/resources/MPA%20Isolation%20Safety%20Poster%20Lo

Videos:
- Conveyor Demonstration Safety Unit: demonstrates hazards of conveyor nip points
https://youtu.be/Ao6nrxgQRjY

- Seven short videos produced by CEMEX
http://www.safequarry.com/toolbox/CEMEXsuiteofvisualaidsonisolationproceduresLO

- Tarmac Isolation Video
https://www.youtube.com/watch?v=qRLvJBV1q1Y

Toolbox Talks: on Conveyor Belt Safety
http://www.safequarry.com/toolbox/Conveyorbeltsafety.pdf