

INCIDENT ALERT

LOCATION: Road transport
ACTIVITY: Transport / Delivery
SUB ACTIVITY: Product delivery

ALERT STATUS: Normal
DATE ISSUED: 11/05/09
INCIDENT No: 00225

TITLE

Concrete Truck Chute

ACCIDENT / INCIDENT DETAILS

Whilst driving over a site speed hump the concrete chute fell open and the locking pin failed causing the chute to swing round.

ACCIDENT / INCIDENT IMAGES



LEARNING POINTS / ACTIONS TAKEN

- L All drivers are reminded of the importance of the regular checking of their vehicles for wear and tear and possible device failures.
- L Possible preventative maintenance techniques should be considered by drivers & replacement of worn parts before failure.
- L Transport departments should be made aware of such issues in order that they may contact manufacturers to try and design out issues.

LEARNING POINTS / ACTIONS IMAGES