

INCIDENT ALERT

LOCATION:
ACTIVITY:
SUB ACTIVITY:

AGGREGATE DREDGER
MARINE OPERATIONS
SHIP TO SHORE

ALERT STATUS:
DATE ISSUED:
INCIDENT No:

Normal
08/01/2013
00354

TITLE

Man Overboard

COUNTRY OF ORIGIN

United Kingdom

ACCIDENT / INCIDENT DETAILS


Whilst putting out the gangway, the Able Seaman pushed the support stanchion which gave way suddenly causing him to fall into the water alongside the ship.

Fortunately he was retrieved from the water quickly. Tide speed and water temperature could have easily made this incident far more serious.

ACCIDENT / INCIDENT IMAGES

Click image to enlarge

The fall was approximately 1 metre



Stanchion which had seized

LEARNING POINTS / ACTIONS TAKEN

Causes and Action:

- Failure to follow the Safe System Of Work – which clearly stated that lifejackets and harnesses should be worn when carrying out this task as well as placing a safety chain across the gap when during the activity.
- Failing to follow and review the Risk Assessment for the task.
- Maintenance procedures need to ensure that moving parts are in good working order.

LEARNING POINTS / ACTIONS IMAGES