

Marine Sand was being loaded out to stock from underneath the radial conveyor when the stockpile failed and material slipped onto the bench and partially onto the floor.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	WHARF	ALERT STATUS:	Normal
ACTIVITY:	STOCKPILING AND STACKING	DATE ISSUED:	13/09/2024 11:38:11
SUB ACTIVITY:	NO SUB ACTIVITY AVAILABLE	INCIDENT No:	03792