## WHAT HAPPENED

Tipper was returning empty to site after delivering a load. As the vehicle slowed to go through traffic lights the 2nd axle nearside wheel came off narrowly missing other vehicles before coming to rest on the side of the road

## LEARNING POINTS / ACTIONS TAKEN

LOCATION: ON-HIGHWAY ACTIVITY: TRANSPORT & LOGISTICS / DELIVERY SUB ACTIVITY: TYRES AND WHEELS ALERT STATUS: DATE ISSUED: INCIDENT No: Normal 30/05/2025 14:05:12 04871