## Pallet falls on roof of fork lift truck whilst destacking

## **WHAT HAPPENED**

Operator destacking/ emptying pallets from the racks inadvertently caught and dragged back a full pallet from the level above which landed on the roof of the FLT damaging and shattering the roof windscreen. The metal pallet then slid down the chassis of the FLT landing on the floor.

## **LEARNING POINTS / ACTIONS TAKEN**

LOCATION: CONCRETE PRODUCTS PLANT ALERT STATUS: Normal

ACTIVITY: STOCKPILING AND STACKING DATE ISSUED: 13/09/2024 13:41:24

SUB ACTIVITY: NO SUB ACTIVITY AVAILABLE INCIDENT No: 04809