

Fire - Flashback - Whilst oxy/fuel gas cutting and lighting the torch, a flashback to the bottle occurred. This was managed / stopped by the arrestor inline system, on the bottle regulator.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION: CONCRETE PRODUCTS PLANT
ACTIVITY: MAINTENANCE & HOUSEKEEPING
SUB ACTIVITY: HOT WORK

ALERT STATUS: Normal
DATE ISSUED: 18/09/2024 13:34:59
INCIDENT No: 04828