

Fire - Fire - A fire started in the cabin of a 360 Excavator, behind the IP. The fire was approximately 3 ft tall and was fully extinguished using 1 extinguisher. No injuries and no damage to the inside of the cab. The excavator contains a fire wall at the rear of the driver.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	QUARRY	ALERT STATUS:	Normal
ACTIVITY:	LOADING AND UNLOADING	DATE ISSUED:	18/09/2024 13:42:53
SUB ACTIVITY:	NO SUB ACTIVITY AVAILABLE	INCIDENT No:	04829