

BEST PRACTICE

LOCATION:
ACTIVITY:
SUB ACTIVITY:
BEST PRACTICE No:
COUNTRY OF ORIGIN:

Quarry
Production and Processing
Aggregate processing
BP2081

ARTICLE YEAR
COMPANY:
COMPANY LOCATION:
COMPANY TEL:

2021
Aggregate Industries
Westleigh Quarry
0000

TITLE

Removal of bucket belt issues and confined space working

ARTICLE

Fatal 1, 4 and 5

Aggregate Industries' Westleigh Quarry had a problem with a bucket belt and straight conveyor that was lifting when empty due to a change in gradient and snagging on the tail drum.

Please click on [additional pdf](#) to download entry in guide

ARTICLE IMAGES

Click image to enlarge

Wheels used on conveyor

Click image to enlarge

