

BEST PRACTICE

LOCATION:	Quarry	ARTICLE YEAR	2006
ACTIVITY:	Worker Involvement	COMPANY:	CEMEX
SUB ACTIVITY:	N/A	COMPANY LOCATION:	Hyndford Quarry, Lanarkshire
BEST PRACTICE No:	BP387	COMPANY TEL:	01555 663597
COUNTRY OF ORIGIN:	United Kingdom		

TITLE

Welfare facilities

ARTICLE

Welfare facilities that had been present at this quarry since the 1960s had become progressively inadequate. With the strong involvement of the workforce, new facilities were developed, including:

- ? Canteen, first aid and training room
- ? Separate toilet and shower facilities for male and female employees
- ? On site water treatment
- ? Power and communication provision
- ? Car access, parking and pedestrian walkways ensuring segregation from large quarry vehicles.

The new buildings feature cavity block walls and tiled roofs with solar panels, which will give them a life-span beyond that of the quarry.

ARTICLE IMAGES