

BEST PRACTICE

LOCATION: Quarry
ACTIVITY: Worker Involvement
SUB ACTIVITY: N/A
BEST PRACTICE No: BP387
COUNTRY OF ORIGIN: United Kingdom

ARTICLE YEAR: 2006
COMPANY: CEMEX
COMPANY LOCATION: Hyndford Quarry, Lanarkshire
COMPANY TEL: 01555 663597

TITLE

Welfare facilities

ARTICLE

Welfare facilities that had been present at this quarry since the 1960s had become progressively inadequate. With the strong involvement of the workforce, new facilities were developed, including:

- ? Canteen, first aid and training room
- ? Separate toilet and shower facilities for male and female employees
- ? On site water treatment
- ? Power and communication provision
- ? Car access, parking and pedestrian walkways ensuring segregation from large quarry vehicles.

The new buildings feature cavity block walls and tiled roofs with solar panels, which will give them a life-span beyond that of the quarry.

ARTICLE IMAGES