## **SHE Alert**

## **LOTOTO – High Potential Near Miss**

## A HiPo near miss occurred when interlocks were used as a form of isolation.

Isolation procedures should always be followed and individual locks attached by anyone entering the area

Limit switches/interlocks must never be used as a form of isolation. These systems break the signals on a control circuit like an emergency stop button.

Try out must always be conducted to ensure the equipment has been successfully isolated.

## **Further Consideration:**

- Ensure anyone working on equipment are trained in LOTOTO.
- 2. Ensure everyone knows the isolation procedures for any plant they work on and where the isolation points are.
- Check everyone/including contractors are following isolation when working on equipment.

