

Isolation Breach - plant was re-energised prior to replacement of the head-drum guard on the batch belt.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	READYMIX OR MORTAR PLANT	ALERT STATUS:	Normal
ACTIVITY:	MAINTENANCE & HOUSEKEEPING	DATE ISSUED:	03/09/2024 16:54:11
SUB ACTIVITY:	CONVEYORS	INCIDENT No:	03734