

Isolation Breach - both wires on the isolator of a hired dewatering pump connected to the same terminal.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	QUARRY	ALERT STATUS:	Normal
ACTIVITY:	MAINTENANCE & HOUSEKEEPING	DATE ISSUED:	03/09/2024 17:31:18
SUB ACTIVITY:	PUMPS	INCIDENT No:	03745