

An unattended landrover rolled approximately 10 metres away striking a conveyor steel support beam.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	QUARRY	ALERT STATUS:	Normal
ACTIVITY:	TRANSPORT & LOGISTICS / DELIVERY	DATE ISSUED:	11/09/2024 18:28:28
SUB ACTIVITY:	DRIVING	INCIDENT No:	03763