

Customer interacted with the telehandler forks, which led to trapping their finger and serious injury.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION: READYMIX OR MORTAR PLANT
ACTIVITY: PEDESTRIAN AND TRANSPORT SAFETY ON-SITE
SUB ACTIVITY: NO SUB ACTIVITY AVAILABLE

ALERT STATUS: Normal
DATE ISSUED: 11/09/2024 18:41:24
INCIDENT No: 03765