

Handrail failure - technician leant on a handrail which sheared from the walkway that he was using to facilitate material testing. This could have resulted in a 2.7m fall from height. Handrail and kicker board heavily corroded.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	QUARRY	ALERT STATUS:	Normal
ACTIVITY:	ACCESS & EGRESS & WORKING AT HEIGHT	DATE ISSUED:	11/09/2024 19:23:25
SUB ACTIVITY:	N/A	INCIDENT No:	03774