

**Marine Sand was being loaded out to stock from underneath the radial conveyor when the stockpile failed and material slipped onto the bench and partially onto the floor.**

## **WHAT HAPPENED**

## **LEARNING POINTS / ACTIONS TAKEN**

---

<b>LOCATION:</b>	<b>WHARF</b>	<b>ALERT STATUS:</b>	<b>Normal</b>
<b>ACTIVITY:</b>	<b>STOCKPILING AND STACKING</b>	<b>DATE ISSUED:</b>	<b>13/09/2024 11:38:11</b>
<b>SUB ACTIVITY:</b>	<b>NO SUB ACTIVITY AVAILABLE</b>	<b>INCIDENT No:</b>	<b>03792</b>