

A lorry was parked side on to a type 1 stock pile to be loaded. A dumper has then tipped a load of type 1 over the edge protection causing it to go underneath the lorry and on the side.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	QUARRY	ALERT STATUS:	Normal
ACTIVITY:	STOCKPILING AND STACKING	DATE ISSUED:	13/09/2024 13:20:52
SUB ACTIVITY:	NO SUB ACTIVITY AVAILABLE	INCIDENT No:	04806