

**RIDDOR - Delivery vehicle had finished tipping off and drove off with body still lifted. The tipper body hit electric cables.**

## **WHAT HAPPENED**

Operatives on site shouted stop, but the driver didn't hear them because he had headphones on. This resulted in him driving through a main overhead electric cable and pulling it down along with the post which snapped in half.

## **LEARNING POINTS / ACTIONS TAKEN**

---

<b>LOCATION:</b>	<b>CONSTRUCTION/DELIVERY SITE</b>	<b>ALERT STATUS:</b>	<b>Normal</b>
<b>ACTIVITY:</b>	<b>TRANSPORT &amp; LOGISTICS / DELIVERY</b>	<b>DATE ISSUED:</b>	<b>18/09/2024 13:08:03</b>
<b>SUB ACTIVITY:</b>	<b>DRIVER AWARENESS</b>	<b>INCIDENT No:</b>	<b>04823</b>